



Model: EXI-800HP Serial #: All	Jun. 27, 2019
Product Bulletin # TDS-200 v 1.0	

Gearbox Upgrade Available

Canrig has discovered that rough drilling and load conditions may cause intermediate gear sets in the EXI-800 top drive gearboxes to experience premature wear. This premature wear may lead to reduced performance prior to Level IV (1000 day) inspections.

Canrig has designed a new, more robust intermediate gear set. Customers may choose to either rework existing intermediate gear sets, or to purchase a new assembly 810375-1. This upgrade is recommended on both new EXI-800 top drives and EXI-600 to EXI-800 conversion top drives.

Canrig recommends that customers contact RIGLINE 24/7™ Support to schedule an upgrade.

Table 1: EXI-800 Gear Set Upgrade

Part No	Qty	Description
5050911-2	1	New EXI-800 Gearbox Assembly
810375-1	1	New EXI-800 Intermediate Shaft Assembly
810373-1	1	New EXI-800 Second Stage Pinion