

## PRODUCT BULLETIN NUMBER: CATWALK 015

PRODUCT: AUTOMATED CATWALKS PC900, PC1000 DATE: 11-Jan-10

SUBJECT: PC900/PC1000 REMOTE MALFUNCTION

SERIAL NUMBERS: PM1000-1001 thru 1027, PC1000-2001 thru 2017, 103019 thru 103032 PC900-1001, 090002 thru 090005

**DISCUSSION:** There has been an incident where the wireless receiver acted irregularly. The operator indicated that there were unwarranted functions occurring when the remote control's functions were not being used.

## **RECOMMENDATION:**

To protect against dropped tubulars Canrig recommends that the existing pipe arm extensions be installed as shown in the attached drawing 188100015 if no pipe racks are being used on that side of the Catwalk.

It is also recommended that the current wiring harness in the receiver, as well as the address chips in the remote and receiver, be replaced with Kit AY50698 to increase the "deadband" and desensitize the paddles. Instructions for the replacement of these parts will be provided with the kit.

Please contact your Field Service Coordinator with the following information to arrange shipment of the warranty Kit AY50698.

Catwalk Serial Number: _	
Radio System Number:	
Nadio System Number.	
Receiver System Numbe	r:





Receiver

## INFORMATION:

For a complete list of all bulletins go to www.canrig.com

For further information contact:

Field Service Canrig Drilling Technology Ltd.

14703 FM 1488 Magnolia, Texas 77354 Phone: 281.259.8887 Fax: 281.259.8158

7475 51 Street SE Calgary, AB T2C 4L6 Phone: 403.237.6400 Fax: 403.536.4605

