

Top Drive Model C500-681 Torque Curve Correction

Issue


The top drive torque curve has been found to be incorrect in several product manuals for the Canrig Model C500-681 made prior to November 11, 2022. See Section 2, page 2-5.


Affected Models

Product manuals made for Models C500-681/1250AC-681, serial number 1411 and older.

Please see corrected torque curve below.

Top Drive Model C500-681 with GE B20 AC Motor





Notes:

- 1. Maximum breakout torque includes the Torque Boost
- 2. This curve is calculated for 45°C (113°F) ambient temperature

Figure 1: Top Drive Model C500-681 Torque curve