



SAFETY BULLETIN – SB003

From: Tesco Products-Applications

Date:

Re: Exhaust Guard Removal

It has recently been reported that the turbo guards have been removed on operating Tesco equipment, in one instance a contributing factor in a fire. This creates a ***burn injury hazard*** or ***fire safety hazard*** and is not an accepted or supported modification to Tesco equipment. ***Under no circumstances will Tesco recommend or support removal of any exhaust safety guards or blankets from operating equipment.***

***If there are any questions related to this Safety Bulletin please contact
Tesco HSE Department.
(403)-233-0757***